



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Anson PERMIT NO.: SLAS 04-08 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 5/03/2013

Date of Last Inspection: 11/26/2012

FACILITY NAME AND ADDRESS:

L & L Environmental Service LLC
 2323 Diggs Road
 Wadesboro, NC 28170

GPS COORDINATES: N: 34.8994 W: -79.9778

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Ronnie & Clay Oaks
 Telephone: (704) 848-8801
 Email address: llenvironmental@gmail.com
 Fax: (704) 848-4522

FACILITY CONTACT ADDRESS:

N/A

PARTICIPANTS:

Connie Wylie, Walter Covington

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. The required signs are posted and the access road is adequate.
2. The approved setbacks are being met.
3. No sign of recent application and no odors noted.
4. Areas that were damaged from hogs were repaired since last visit.
5. The fescue is tall on the disposal fields but Mr. Covington indicated that it was about to be cut.
6. Discussed field markers with Mr. Covington, it appears that there may be some missing markers at the swale on field 1. Did not ride over entire site due to recent heavy rains.

Please contact me if you have any questions or concerns regarding this inspection report.



Connie S. Wylie
Regional Representative

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	X	US Mail		Certified No. <u> </u>
----------	--	-------	--	---------------	---	---------	--	-------------------------